

Bridge 101

2019 County Roads Conference

January 29-31, 2019


Bryon Fuchs, PE

Information was provided by:


Gary Doerr, PE – NDDOT & Dale Heglund, PE - NDLTAP

Bridge Personnel Change







County Bridges Year Built





Type of Bridges



What is a Bridge?














Buried Bridges

Minor Structures

Less than 20' in length


BRIDGE COMPONENTS AND TERMS

- Three Major Bridge Components
 - Deck
 - Superstructure
 - Substructure




DECK

- Portion of the bridge that you drive on




SUPERSTRUCTURE

- Portion of the bridge that lies directly below and supports the deck
 - Beams, girders, truss, arch




SUBSTRUCTURE

- Portion of the bridge that supports the deck and superstructure.
 - Abutments, piers



Load Rating of Bridges



Dead Load

Gravel

Asphalt

Combination






Overburden




Dynamic Impact Loads

What is it?


Smooth ride solution



Truck



Truck pulling one trailer.



Truck pulling two trailers.




Truck-tractor pulling one semitrailer.




"Double Bottom"

Truck-tractor pulling one semitrailer and one trailer or semitrailer converted to a trailer with a dolly.



Truck-tractor pulling one semitrailer and two trailers or semitrailers converted to trailers with dollies.

"Triple Bottom"




"B" Train

Truck-tractor pulling two semitrailers.

Bridge Inspections

NDDOT/FHWA Inspections

- Federally mandated
- Includes both NDDOT and City/County bridges
- Normal frequency - 2 years
 - Alert Code 3 Structures - annually
- Special frequency – 4 years (box culverts)



Inspection Terms

- The **SUFFICIENCY RATING** of a bridge is a single number from 0 (low) to 100 (high) taking into account, bridge condition, geometry, traffic, and how well the waterway passes underneath the bridge. Sufficiency rating is used to determine funding eligibility. A low sufficiency rating does not necessarily mean the bridge is unsafe or in need of immediate repair.
- A **FRACTURE CRITICAL MEMBER** is a steel member in tension that does not have enough additional, structural members to sufficiently redistribute load in the bridge if one member loses capacity, thus resulting in a portion of or entire bridge collapse.
- **FATIGUE** is a material response that describes the tendency of a material to break when subjected to repeated loading.

Inspection Terms

- Bridges are considered **STRUCTURALLY DEFICIENT** if significant load-carrying elements are found to be in poor or worse condition due to deterioration and/or damage, or the adequacy of the waterway opening provided is determined to be extremely insufficient. The fact that a bridge is structurally deficient does not immediately imply that it is likely to collapse or that it is unsafe.
- Bridges are considered **FUNCTIONALLY OBSOLETE** when the geometry of the roadway no longer meets today's minimum design standards for width or vertical clearance for that roadway classification, or the adequacy of the waterway opening provided is determined to be insufficient. The fact that a bridge is functionally obsolete does not imply that it is unsafe.

Structural Inventory and Appraisal Sheet

SI&A Sheet

January 13, 2016

North Dakota Department of Transportation Bridge Inventory - Structure Inventory And Appraisal Sheet

SEC 409

Structure Number:	18-113-28.1	chaindate
200 System Designation	3 - County Off	Classification
201 Status	Not Deficient	12 Base Highway Network
202 Sufficiency Rating	62.00	20 Toll
Identification		21 Maint Responsibility
02 Highway District	Grand Forks District	22 Owner
03 County	Gr. Forks	26 Functional
04 City	GRACE TOWNSHIP	37 Historical Significance
05 Inventory Route	Route On Structure	100 Defense Highway Designation
4 County Hwy	1 Mainline 00000 0 N/A (NBI)	101 Parallel Structure Designation
06 Feats Intersect	CREEK	102 Direction of Traffic
09 Location	2 SOUTH 1 WEST KEMPTON	103 Temporary Structure Designation
11 Milepoint	0.000	104 Highway System of Inventory Rte
13 LRS Inv Route, Subroute	-1 -1	105 Federal Lands Highways
16 Latitude	47d 47' 16.00"	110 Designated National Network
17 Longitude	97d 38' 36.00"	112 NBIS Bridge Length
GPS Coordinates XY	601621.7 5293591.9	226 Functional Under
98 Border Bridge	Unknown (P) 0.00 %	Condition
99 Border Bridge Struct No.	-	58 Deck
Structure Type and Material		59 Superstructure
43 Main Struct Type	Steel	60 Substructure
Stringer		61 Chan. & Chan. Protection
44 Approach Struct Type	Unknown (NBI)	62 Culvert and Retaining Walls
	Unknown (P)	Load Rating and Posting
45 No. Spans in Main Unit	1	31 Design Load
46 No. Approach Spans	0	M 18 (H 20) (live load for which structure was designated)
107 Deck Struct Type	8 Wood or Timber	41 Structure Open, Closed or Posted
108 Wearing Surface	7 Wood or Timber	63 Operating Rating Method
Membrane	0 None	64 Oper. Rating HS 14
Dk Protect	None	65 Inventory Rating Method
208 Dk Overburden	205 Gravel/Dirt	66 Inv. Rating HS 9
Age and Service		70 Bridge Posting
27 Yr Built	1949 106 Yr Reconstructed -1	209 Posted in "Tons"
42 Type of Service	1 Highway - On	Appraisal
	5 Waterway - Under	67 Structural Condition
28 Lanes on Structure	2	68 Deck Geometry
29 ADT	30 30 Year of ADT 2013	69 Underclear, Vert & Horiz
109 Average Daily Truck Traffic	-1.00	71 Waterway Adequacy
19 Bypass, Detour Length	2 Miles	72 App. Rdwy. Alignment
Geometric Data		36 Traffic Safety Features
10 Min Vert Clearance	328 Ft. 1 In.	113 Scour Critical
32 Approach Roadway Width	20 Feet	Inspections
33 Bridge Median	0 No median	90 Date of Last Inspection
34 Skew	0.00	91 Designated Inspection Frequency
35 Structure Flared	0 No flare	92 Critical Feature Inspected / 93 Critical Feature Last Inspection Dt
47 Total Horizontal Clearance	25.3 Feet	Fracture Critical N
48 Length of Max Span	26 Feet	Underwater N
49 Structure Length	29.86 Feet	Other Special N
50 Curb/Sidewalk Widths	0.3 FT RT-Side	218 Channel Profile Y 48
	0.3 FT Lt-Side	Chaining Date
51 Bridge Rdwy Width - Curb to Curb		207 Transporter Erector Routes and Sites
	25.3 Feet	212 Structure Load Rated
52 Deck Width	26.2 Feet	213 Federal Aid Project Number
53 Min Vert Clear, Over Bridge	328 Ft. 1 In.	214 Delayed Inspection
54 Min Vert Underpassage	0 Ft. 0 In.	



March 09, 2017

North Dakota Department of Transportation
Bridge Inventory - Structure Inventory And Appraisal Sheet

SEC 409

Structure Number: 05-147-19.0

200 System Designation 3 – County Off
 201 Status Not Deficient
 202 Sufficiency Rating 63.30

Identification

02 Highway District Minot District
 03 County Bottineau
 04 City OAK VALLEY TOWNSHIP
 05 Inventory Route Route On Structure
 4 County Hwy 1 Mainline 00000 0 N/A (NBI)
 06 Feats Intersect DRAINAGE DITCH
 09 Location 2 NORTH 1 EAST OF GARDENA
 11 Milepoint 0.000
 13 LRS Inv Route. Subroute -1 -1
 16 Latitude 48d 44' 02.00"
 17 Longitude 100d 28' 53.00"
 GPS Coordinates XY 391084.1 5398918.9
 08 Border Bridge Unknown (P) 0.00 %

Bridge Struct No. -
Structure Type and Material

Classification

12 Base Highway Network Not on Base Network
 20 Toll 3 On free road
 21 Maint Responsibility 02 County Hwy Agency
 22 Owner 02 County Hwy Agency
 26 Functional Rural, Local
 37 Historical Significance 3 Possibly eligible for
 100 Defense Highway Designation 0 Not a STRAHNET hwy
 101 Parallel Structure Designation No || bridge exists
 102 Direction of Traffic 2 2-way traffic
 103 Temporary Structure Designation Not Applicable (P)
 104 Highway System of Inventory Rte 0 Not on NHS
 105 Federal Lands Highways Not applicable
 110 Designated National Network 0 Not part of natl netwo
 112 NBIS Bridge Length Yes

Condition

58 Deck 7 Good
 59 Superstructure 6 Satisfactory
 60 Substructure 6 Satisfactory



Structure Type and Material

43 Main Struct Type	Wood or Timber
Stringer	
44 Approach Struct Type	Unknown (NBI)
	Unknown (P)
45 No. Spans in Main Unit	2
46 No. Approach Spans	0
107 Deck Struct Type	8 Wood or Timber
108 Wearing Surface	8 Gravel
Membrane	0 None
Dk Protect	None
208 Dk Overburden	205 Gravel/Dir

Age and Service

27 Yr Built	1935	106 Yr Reconstructed	-1
42 Type of Service		1 Highway - On	
		5 Waterway - Under	
28 Lanes on Structure			2
29 ADT	25	30 Year of ADT	2016
109 Average Daily Truck Traffic			-1.00
19 Bypass, Detour Length		2 Miles	

60 Substructure	6 Satisfactory
61 Chan. & Chan. Protection	7 Minor Damage
62 Culvert and Retaining Walls	N N/A (NBI)

Load Rating and Posting

31 Design Load		Unknown
41 Structure Open, Closed or Posted		P Posted for load
63 Operating Rating Method		2 AS Allowable Stress
64 Oper. Rating	HS 11	19 Tons
65 Inventory Rating Method		2 AS Allowable Stress
66 Inv. Rating	HS 7	13 Tons
70 Bridge Posting		0 >39.9% below
209 Posted in "Tons"		10 Tons

Appraisal

67 Structural Condition	4 Minimum Tolerable
68 Deck Geometry	5 Above Tolerable
69 Underclear. Vert & Horiz	N Not applicable (NBI)
71 Waterway Adequacy	6 Equal Minimum
72 App. Rdwy. Alignment	7 Above Min Criteria
36 Traffic Safety Features	0 0 0 0

Geometric Data		113 Scour Critical	U Unknown Scour	
10 Min Vert Clearance	99 Ft. 12 In.	Inspections		
32 Approach Roadway Width	16 Ft.	90 Date of Last Inspection	October 11, 2016	
33 Bridge Median	0 No median	91 Designated Inspection Frequency	24 Months	
34 Skew	0.00	92 Critical Feature Inspected / 93 Critical Feature Last Inspection Dt		
35 Structure Flared	0 No flare	Fracture Critical	N	
47 Total Horizontal Clearance	23.0 Ft.	Underwater	N	
48 Length of Max Span	13 Ft.	Other Special	N	
49 Structure Length	29.86 Ft.	218 Channel Profile	Y	48 08/16/2013
50 Curb/Sidewalk Widths	0.7 Ft Rt-Side	Chaining Date	None	
	0.7 Ft Lt-Side	207 Transporter Erector Routes and Sites -1		
51 Bridge Rdwy Width - Curb to Curb		212 Structure Load Rated	01/01/1901	
	23.0 Ft.	213 Federal Aid Project Number		
52 Deck Width	24.3 Ft.	214 Delayed Inspection	Not Applicable	
53 Min Vert Clear. Over Bridge	99 Ft. 12 In.	216 Inspector	Olson, Lawson	
54 Min Vert Underclearance	0 Ft. 0 In.	Navigation Data		
	N Feature not hwy or RR	38 Navigation Control	Permit Not Required	
55 Min Lateral UnderClear. - Rt	99.9 Ft.	39 Navigation Vertical Clearance	0 Ft.	
	N Feature not hwy or RR	40 Navigation Horizontal Clearance	0 Ft.	
56 Min Lateral UnderClear. - Lt	0.0 Ft.	111 Pier or Abutment Protection	Unknown (NBI)	
210 Culvert / 211 Description		116 Minimum Navigation Vertical Clearance	-1 Ft.	

March 09, 2017

North Dakota Department of Transportation
 Bridge Inventory - Structure Inventory And Appraisal Sheet

SEC 409

Structure Number: 05-147-19.0


Element / Env. / Description	Units	Total Qty	1 %	1-Qty St	2 %	2-Qty St	3 %	3-Qty St	4 %	4-Qty St
111/1:Timber Open Girder	ft	689	0	0	98	676	2	13	0	0
1150/1:Check/Shake	each	676	0	0	100	676	0	0	0	0
1160/1:Crack (Timber)	each	13	0	0	0	0	100	13	0	0
206/1:Timber Column	each	18	0	0	100	18	0	0	0	0
1150/1:Check/Shake	each	18	0	0	100	18	0	0	0	0
216/1:Timber Abutment	ft	49	0	0	100	49	0	0	0	0
1150/1:Check/Shake	each	49	0	0	100	49	0	0	0	0
235/1:Timber Pier Cap	ft	72	0	0	100	72	0	0	0	0
1150/1:Check/Shake	each	72	0	0	100	72	0	0	0	0
31/1:Timber Deck	sq.ft	689	0	0	100	689	0	0	0	0
332/1:Timb Bridge Railing	ft	59	0	0	49	29	0	0	51	30

31/1:Timber Deck	sq.ft	689	0	0	100	689	0	0	0	
332/1:Timb Bridge Railing	ft	59	0	0	49	29	0	0	51	30
1150/1:Check/Shake	each	29	0	0	100	29	0	0	0	
7000/1:Damage	each	30	0	0	0	0	0	0	100	30
8401/1:Wings	each	4	75	3	25	1	0	0	0	

Remarks: TIMBER CURBS HAVE MINOR TO MODERATE DAMAGE. TOPS OF WINGS HAVE MINOR SNOW PLOW DAMAGE. PLANK AT GIRDER ENDS HAS SLIPPED DOWN, ALLOWING SOIL TO BUILD UP ON ABUTMENT CAPS. ALL STRUCTURAL MEMBERS ARE WEATHER CHECKED. SILT BAR BUILDING UP IN WEST SPAN. GIRDER 17 FROM NORTH HAS LONGITUDINAL CRACK. GIRDER 13 HAS DEEP WEATHER CHECK. EAST ABUTMENT CAP HAS DEEP WEATHER CHECK ON ITS VERTICAL FACE. Pier 2 has minor damage at both ends from debris. West abutment bottom horizontal plank is cracked 3'-4', north end. Small void behind west abutment south end where ties to wing. NO END MARKERS.

Alert Code 1: Small sink holes at west end of bridge behind abutment in wheel paths.

Sufficiency Rating



4. SPECIAL REDUCTIONS
 $S_4 = 13\% \text{ Max.}$

- 19 Detour Length
- 36 Traffic Safety Features
- 43 Structure Type, Main

SUFFICIENCY RATING = $S_1 + S_2 + S_3 - S_4$

Sufficiency Rating shall not be less than 0% nor greater than 100%

Inspections Part #2

The Important Paperwork

Paperwork

- Load Posting Requirement
- Alert Code 3 notification
- Scour & Channel Profiles Due
- Bridge Location Maps

TO: Bottineau County
FROM: Paul Benning, Local Government
DATE: March 31, 2017
SUBJECT: Bridge Requiring Load Limit Posting

TO: Bottineau County
FROM: Paul Benning, Local Government
DATE: March 31, 2017
SUBJECT: Bridge Requiring Load Limit Posting

Bridge Number: 05-157-28.0
Location: 2E OF WILLOW CITY

SUBJECT: Bridge Requiring Load Limit Posting

According to the latest bridge inspection and inventory data 05-157-28.0 lacks proper Load Limit Signs. FHWA Regulation of less than legal loads must be posted for a Load Limit that in North Dakota is an HS20 truck which weighs 36 tons. Signs must have Load Limit Signs.

Bridge Number: 05-157-28.0
Location: 2E OF WILLOW CITY

Bridge number 05-157-28.0 has an Operating Rating of 17.0 Tons. It is your option to post the bridge at any tonnage you maximum operating tonnage. Two types of signs (shown on drivers with a more consistent messages statewide. Please or bridge.

According to the latest bridge inspection and inventory data on record with the Bridge Division, bridge number 05-157-28.0 lacks proper Load Limit Signs. FHWA Regulations require that any bridge with an operating rating of less than legal loads must be posted for a Load Limit that does not exceed the Operating Rating. The legal load in North Dakota is an HS20 truck which weighs 36 tons. Since bridge number 05-157-28.0 is less than 36 tons, it must have Load Limit Signs.

Bridge number 05-157-28.0 is posted at _____
Type of sign used (R12-1, R12-4, or Other) _____
Date Bridge was posted: _____

Other Remarks: _____

Bridge number 05-157-28.0 has an Operating Rating of 17.0 Gross Tons and an Inventory Rating of 10.0 Gross Tons. It is your option to post the bridge at any tonnage you want as long as it is equal to or less than the maximum operating tonnage. Two types of signs (shown on attachment) are recommended in order to provide drivers with a more consistent messages statewide. Please complete the following after you have posted this bridge.

Work Done By Whom: _____
If you have any questions, please call me at 328-4334. Please Appreciated) to:

Local Government
ND Department of
608 East Boulevard
Bismarck, North D

Bridge number 05-157-28.0 is posted at _____ Ton:

Type of sign used (R12-1, R12-4, or Other) _____

Date Bridge was posted: _____

INSTRUCTIONS FOR POSTING WEIGHT LIMITS
ON
COUNTY BRIDGES

- Priority I Post all unposted bridges as soon as possible (data from last inventory provided).
- Priority II Update signs as conditions or re-rating change present weight limits.

NOTE: All bridges should be posted using one of the following sign types. Either the inventory ton or the operating ton is the maximum posting to be used. The choice of which one is left up to your discretion at each bridge site.

- A. The new rating is in the HS format (e.g. the first digit is a 2). If the last two digits are less than 36 and more than 21, then post by using sign R12-1.

Examples: Where range is above 21 or less than 36

WEIGHT LIMIT 22 TONS	WEIGHT LIMIT 22 TONS	WEIGHT LIMIT 22 TONS	WEIGHT LIMIT 22 TONS
-------------------------------	-------------------------------	-------------------------------	-------------------------------

(all are R12-1 24"x30")

- B. The new rating is in the HS format (e.g. the first digit is a 2). If the last two digits are 21 or less, then post by using sign R21-4.

Examples: Where range is 21 or less

WEIGHT LIMIT 2 TONS PER AXLE 5 TONS GROSS	WEIGHT LIMIT 5 TONS PER AXLE 12 TONS GROSS	WEIGHT LIMIT 9 TONS PER AXLE 21 TONS GROSS
---	--	--

[0.444x5=2 (max/axle)]

[0.444x12=5 (max/axle)]

[0.444x21=9 (max/axle)]

(All are R12-4 36"x24")



Alert Codes

FHWA requires that there is a follow-up procedure for bridges that have been identified with the alert code 3 status (immediate attention required). To comply with the FHWA requirement, NDDOT is requesting each owner of a bridge with an alert code 3 to use this report format to identify action taken to address the alert code 3 condition. This should be done by July 15, 2017. The following is the alert code remarks section from the Structure Inventory and Appraisal sheet for the subject bridge that requires attention:

TO: Dickey County
FROM: Paul Benning, Local Government
DATE: March 31, 2017

SUBJECT: Follow-up on Bridges with Alert Code 3 - IMMEDIATE ATTENTION

Bridge Number: 11-123-08.0
Location: 3 EAST 1 NORTH MONANGO

FHWA requires that there is a follow-up procedure for bridges that have been identified with the alert code 3 status (immediate attention required). To comply with the FHWA requirement, NDDOT is requesting each owner of a bridge with an alert code 3 to use this report format to identify action taken to address the alert code 3 condition. This should be done by July 15, 2017. The following is the alert code remarks section from the Structure Inventory and Appraisal sheet for the subject bridge that requires attention:

Remarks: NBI Remarks: Spalling thru-out structure. Exposed steel on east curb. West railing bent. Poor stream alignment. Road posted for 30 mph. Exposed rebar throughout structure exposed rebar west curb north end. .

Alert Code 3: 1/2016 - South diaphragm has a longitudinal crack.

Below describes what work or (repairs or other action) was done by the county to alleviate the cause of the alert code 3. Also describe any other work that you've done on this bridge that would affect the condition ratings or the load ratings.

Work Done By Whom: _____ On Date: _____

If you have any questions, please call me at 328-4334. Please return this form by July 15, 2017 (Earlier Response Appreciated) to:

Local Government Division
ND Department of Transportation
608 East Boulevard Ave.
Bismarck, North Dakota 58505-0700

Scour Surveys

Turned over to the
Counties in 1995

Required every 4 years

March 31, 2017
Bottineau County

North Dakota Department of Transportation
Bridge Inventory - Scour and Channel Profile

Page 5 of 54
SEC 409

Structure Number	Location	Feature Intersected	Channel Profile		Year Built	Structure Type
			Last Inspected	Frequency		
05-101-14.0	12 NORTH 4 WEST LANSFORD	WEST CUT BANK CREEK	08/23/2013	48	1945	Wood or Timber - Stringer
05-101-15.0	11 NORTH 5 WEST LANSFORD	CREEK	08/26/2013	48	1955	Concrete - Channel Bm
05-102-14.0	2 EAST 3 NORTH OF MOHALL	WEST CUT BANK CREEK	08/23/2013	48	1970	Concrete - Channel Bm
05-103-12.0	8 SOUTH 6 WEST ANTLER	CUT BANK CREEK	08/23/2013	48	1969	Prestressed conc - Adjacent Box Bm
05-103-15.0	3 EAST 2 NORTH OF MOHALL	CUT BANK CREEK	08/23/2013	48	1965	Concrete - Channel Bm
05-104-12.0	14 NORTH 1 WEST LANSFORD	CUT BANK CREEK	08/26/2013	48	1948	Wood or Timber - Stringer
05-105-14.0	12 NORTH 1 WEST LANSFORD	CUT BANK CREEK	08/23/2013	48	1970	Concrete - Channel Bm
05-107-09.0	6 SOUTH 3 WEST OF ANTLER	CREEK	08/23/2013	48	1935	Wood or Timber - Stringer
05-108-20.0	6 NORTH 3 EAST LANSFORD	CUT BANK CREEK	06/23/2014	48	1949	Wood or Timber - Stringer
05-108-21.0	8 WEST OF MAXBASS	CUT BANK CREEK	08/20/2013	48	1948	Wood or Timber - Stringer
05-109-01.0	2 NORTH 1 WEST OF ANTLER	ANTLER CREEK	08/23/2013	48	1939	Wood or Timber - Stringer
05-109-12.0	9 SOUTH OF ANTLER	CREEK BED	08/23/2013	48	1950	Wood or Timber - Stringer


March 31, 2017
Dickey County

North Dakota Department of Transportation
Bridge Inventory - Scour and Channel Profile

Page 12 of 54
SEC 409


Structure Number	Location	Feature Intersected	Channel Profile		Year Built	Structure Type
			Last Inspected	Frequency		
11-145-03.0	7 N 1 E OF OAKES	CREEK	06/12/2013		1976	Prestressed conc - Tee Bm

County Structures Due for Channel Profile: 1



Scour and Channel Profile

2-187.740 R
North SIDE



Bridge Inspection

County pays 19.07% match for NDDOT inspection = \$45.20/structure


Box Culvert Inspection Cycle

January 13, 2016 North Dakota Department of Transportation
 Bridge Inventory - Structure Inventory And Appraisal Sheet SEC 408


Structure Number:	18-113-28.1	chaindate	
200 System Designation	3 - County Off	Classification	
201 Status	Not Deficient	12 Base Highway Network	Not on Base Network
202 Sufficiency Rating	62.00	20 Toll	3 On free road
Identification		21 Maint Responsibility	02 County Hwy Agency
02 Highway District	Grand Forks District	22 Owner	02 County Hwy Agency
03 County	Gr. Forks	26 Functional	Rural, Local
04 City	GRACE TOWNSHIP	37 Historical Significance	5 Not eligible for NRHP
05 Inventory Route	Route On Structure	100 Defense Highway Designation	0 Not a STRAHNET hwy
4 County Hwy	1 Mainline 00000 0 N/A (NBI)	101 Parallel Structure Designation	No bridge exists
06 Feats Intersect	CREEK	102 Direction of Traffic	2 2-way traffic
09 Location	2 SOUTH 1 WEST KEMPTON	103 Temporary Structure Designation	Not Applicable (P)
11 Milepoint	0.000	104 Highway System of Inventory Rte	0 Not on NHS
13 LRS Inv Route, Subroute	-1 -1	105 Federal Lands Highways	Not applicable
16 Latitude	47d 47' 16.00"	110 Designated National Network	0 Not part of nati netwo
17 Longitude	97d 38' 36.00"	112 NBIS Bridge Length	
GPS Coordinates XY	601621.7 5293591.9	226 Functional Under	
98 Border Bridge	Unknown (P)	0.00 %	Condition
99 Border Bridge Struct No.	-	58 Deck	7 Good
Structure Type and Material		59 Superstructure	6 Satisfactory
43 Main Struct Type	Steel	60 Substructure	5 Fair
Stringer		61 Chan. & Chan. Protection	7 Minor Damage
44 Approach Struct Type	Unknown (NBI)	62 Culvert and Retaining Walls	N N/A (NBI)
45 No. Spans in Main Unit	1	Load Rating and Posting	
46 No. Approach Spans	0	31 Design Load	M 18 (H 20) (live load for which structure was designated)
107 Deck Struct Type	8 Wood or Timber	41 Structure Open, Closed or Posted	P Posted for load
108 Wearing Surface	7 Wood or Timber	63 Operating Rating Method	2 AS Allowable Stress
Membrane	0 None	64 Oper. Rating	HS 14 26 Tons
Dk Protect	None	65 Inventory Rating Method	2 AS Allowable Stress
208 Dk Overburden	205 Gravel/Dir	66 Inv. Rating	HS 9 17 Tons
Age and Service		70 Bridge Posting	2 20.0-29.9%below
27 Yr Built	1949 106 Yr Reconstructed -1	209 Posted in "Tons"	27 Tons
42 Type of Service	1 Highway - On	Appraisal	
28 Lanes on Structure	5 Waterway - Under	67 Structural Condition	4 Minimum Tolerable
29 ADT	30 30 Year of ADT 2013	68 Deck Geometry	6 Equal Min Criteria
109 Average Daily Truck Traffic	-1.00	69 Underclear, Vert & Horiz	N Not applicable (NBI)
19 Bypass, Detour Length	2 Miles	71 Waterway Adequacy	8 Equal Desirable
Geometric Data		72 App. Rdwy. Alignment	6 Equal Min Criteria
10 Min Vert Clearance	328 Ft. 1 in.	36 Traffic Safety Features	0 0 0 0
32 Approach Roadway Width	20 Feet	113 Scour Critical	U Unknown Scour
33 Bridge Median	0 No median	Inspections	
34 Skew	0.00	90 Date of Last Inspection	September 02, 2015
35 Structure Flared	0 No flare	91 Designated Inspection Frequency	24 Months
47 Total Horizontal Clearance	25.3 Feet	92 Critical Feature Inspected / 93 Critical Feature Last Inspection Dt	
48 Length of Max Span	26 Feet	Fracture Critical	N
49 Structure Length	29.86 Feet	Underwater	N
50 Curb/Sidewalk Widths	0.3 Ft Rt-Side 0.3 Ft Lt-Side	Other Special	N
51 Bridge Rdwy Width - Curb to Curb	25.3 Feet	218 Channel Profile	Y 48 09/19/2013
52 Deck Width	26.2 Feet	Chaining Date	None
53 Min Vert Clear. Over Bridge	328 Ft. 1 in.	207 Transporter Erector Routes and Sites	-1
54 Min Vert Underclearance	0 Ft. 0 in.	212 Structure Load Rated	01/01/1901
55 Min Lateral UnderClear. - Rt	N Feature not hwy or R/R	213 Federal Aid Project Number	
56 Min Lateral UnderClear. - Lt	0.0 Feet	214 Delayed Inspection	Not Applicable
210 Culvert / 211 Description		Navigation Data	Fischer
		216 Inspector	
		36 Navigation Control	Permit Not Required
		38 Navigation Vertical Clearance	0 Feet
		40 Navigation Horizontal Clearance	0 Feet
		111 Pier or Abutment Protection	Unknown (NBI)
		116 Minimum Navigation Vertical Clearance	



New Bridge Process



Bridge Removal Process



Structure Inspection Notification

County			
Structure Number			
Location			
Reason for inspection (new/rehabilitation/repair)			
Who performed the work?			
Was Structure previously closed? (y/n)		If so, when?	
Date work was completed		Currently posted for Load? (y/n)	
Location of Work Performed			
<i>Work performed on the following areas of the Structure</i>			
Deck (y/n)		Pier(s) (y/n)	
Beam/Girder (y/n)		Abutment(s) (y/n)	
Pier/Abutment Caps (y/n)		Channel (riprap) (y/n)	
Other			
<i>Was the work completed due to an Alert Code on the SI&A sheet (y/N)</i>			
If yes, what Alert Code was repaired			
<i>What work was completed on this Structure</i>			
<i>Materials used (provide a description of the material properties, size, etc.)</i>			








The Bismarck Tribune

Rewriting legislation
Senate Bill 2344 would change language of Measure 5



SUNNY 15 • 6 FORECAST, B6 | FRIDAY, FEBRUARY 3, 2017 | bismarck




TOM STROMME PHOTOS, TRIBUNE

Truck with an oversize load struck the underside of a bridge over Interstate 94 near mile marker 129 on Wednesday, leaving extensive damage to the underside of the overpass near McKenzie. The bridge, closed indefinitely until repairs can be made, carried local traffic on 275th Street Northeast in rural Bismarck.

Truck crashes into bridge







10/20/2017

Bridge in rural N.D. collapses under weight of truck | INFORUM

INFORUM

Bridge in rural N.D. collapses under weight of truck

By Forum News Service Today at 6:28 a.m.

64




FOREST RIVER, N.D. - A semi driver is lucky to be safe after a bridge caved while crossing it.

A woman who lives nearby the crash site, Holly Beaton, says it happened around 10 a.m. Thursday, Oct. 19 near Forest River.

The truck appears to have been hauling grain when the bridge gave out, causing the cab of the truck to be caught in the air.

Beaton says the driver made it out safely, and the sheriff's office told her the truck will be stuck in the bridge for a few days while they










Barnes County – Timber Box Culvert




Stark County Bridge Replacement



Structure #: 34-112-03.0
Pier Unevenly Loaded with
Embankment and Riprap
Causing Horizontal Cracking
in Pier
Face South
Date 11/13/2006



Bridge # 32-119-35.0
Direction: North
Sediment and Tree Debris
Built Up Against West Side of
Pier. Note Farmers Fence Across
Channel Span
02/25/05






Structure # 50-153-22.0
Another View
Face NE
Date: 09/18/2007



11.13.2006
NDOT
North Dakota
Department of Transportation













Questions?

Thank you!!

Bryon Fuchs, PE

701-328-2516

blfuchs@nd.gov