Texas Underseal

Tyler Wollmuth, P.E.

NDDOT – Bismarck District



Who?

➤ 2015 North Dakota Asphalt Conference – April 1, 2015

Tom Wood, MNDOT Research Project Supervisor gave a presentation

➤ NDDOT Transportation Innovation Program (TRIP)

Steph Weigel, NDDOT submitted the idea in April 2015

Added to ND 22 project by addendum prior to May 2015 bid opening

More Who?

- Prime Contractor: Knife River Corp.
- > Chip Seal Contractor: Asphalt Surface Technologies
- > Project Designer: Jason Fischer, Dickinson District
- Project Engineer: Dan Schneider, AECOM
- Consultant Oversight: Tyler Wollmuth, Bismarck District

What?

- "Underseal" is an application of a chip seal coat prior to overlaying the pavement to provide an impervious membrane to stop the intrusion of moisture.
- ➤ In Texas, the #1 usage is to prevent intrusion of surface water into underlying layers of asphalt. While using the underseal they found a 2nd benefit which was delayed reflection cracking.

Credit: Report FHWA/TX-06/0-4391-1 - Guidelines for the use of underseals as a pavement moisture barrier published in November 2006

Where?

Project SOIB-5-022(092)000RP 0.00 to RP 11.918

Underseal Test Section RP1.497 to RP 6.171

Control SectionRemainder of Project




Why?


> MNDOT started using this process and found the delayed reflective cracking beneficial.

> 5-6 years before thermal cracks reflected thru the pavement when undersealed as compared to 1-2 years on a typical HMA overlay.

"We don't know why it works, but it just does" - Tom Wood, MNDOT



How?



Project Specifics

- ➤ Milling 1" Depth
- Chip Seal
 Design application rate
 CRS2P = 0.35 GAL/SY
 Actual application rate
 CRS2P = 0.343 GAL/SY
 CL 41 = 18 LBS/SY
- > Additional Cost of Underseal: \$29,027 / Mile
- 3" HMA Overlay2 equal lifts of RAP Superpave FAA 45 with PG 64-28 Asphalt Cement

Ride (IRI) Results

<u>Mile</u>	Before	After	2017
0	241	41	61
1	220	40	61
2	209	33	54
3	203	34	52
4	181	34	52
5	203	32	54
6	298	33	50
7	200	30	59
8	197	28	47
9	268	29	48
10	262	29	58
11	197	47	57



What we have learned

➤ NDDOT will monitor for 5-6 years



- Field Review on February 25, 2016 showed that no cracks had reflected thru the new pavement, but there was a noticeable difference in ride from underseal to control.
- Field Review on March 16, 2017 showed that the transverse cracks have reflected thru the pavement but the number and severity of cracks is less in the underseal section.

Questions?

