

SHARETHE

Agriculture Transportation Safety





Safe Procedures for Public Roadway Travel

- Avoid transporting equipment during:
 - Low visibility conditions
 - Low light (generally 1 hour before sunset to 1 hour after sunrise)
 - Other weather conditions (fog, rain, snow)
- Transporting over-weight loads
 - Be aware of bridge and road weight limits
 - Match tractor weight to load weight
- Transporting over-width equipment
 - Use transport position
 - Use optional pilot vehicle
 - Use warning lights
- Spilled/hazardous material
 - Call 911
 - Must be 18 in North Dakota to transport





Meeting oncoming traffic

- Stay in proper traffic lane
- Slow down and utilize shoulder if available

Accumulating traffic to the rear

Pull onto shoulder to allow traffic to pass, preferred at each mile traveled

Crossing unprotected railroad tracks

Stop and look both ways

Making left turns

- May require pilot car or someone to direct traffic
- Use turn signal, if equipped

NOTE: An alternative route may be safer!



